

1028, 1057, 1058, 1059 Sensors

Used on Honda, Kia, and Hyundai vehicles



1028 Sensor
(Lear)



1057-1059 Sensors
(Entire)

Sensors use either 1096 or 1097 Metal Valves



1096 short metal valve



1097 long metal valve

2000K

Or you can simply replace the components,
2000K fits all sensors/valves shown above.

